


Oct 2020



Issue to resolve

- Instal DUST COVER on FirePro Unit
- Replace Linear Heat Detection Cable with DP Version