


Oct 2020



Issue to resolve

- Resolve mounting location for FP Unit – not as per drawing
- Resolve Mounting Location for Panel – not as per drawing
- Plastic Cover over Control Panel