

Feb 2021



Issue to resolve

- Resolve mounting location for FP Unit – not as per drawing
- Resolve Mounting Location for Panel – not as per drawing
- Plastic Cover over Control Panel

- Change to NiMH Battery