


Nov 2020



Issue to resolve

- Resolve mounting location for FP Unit – not as per drawing
- Resolve Mounting Location for Panel – not as per drawing
- Resolve mounting location of Siren Strobe – not as per drawing